

US regulators will force Boeing to rewire 737 MAX jets: report

March 9 2020



The MAX has been grounded worldwide since an Ethiopian Airlines flight crashed shortly after take-off last March

US aviation regulators plan to require Boeing to rewire all 737 MAX aircraft before allowing the troubled planes fly again, the Wall Street

Journal has reported.

The MAX has been grounded worldwide since an Ethiopian Airlines flight crashed shortly after take-off last March, less than six months after the same model was involved in a similar fatal accident in Indonesia.

Both accidents saw uncontrolled drops in the [aircraft](#)'s nose in the moments before the planes crashed, which investigators have blamed on the model's anti-stall flight system.

Regulators have since concluded that the current wiring layout violated [safety standards](#) to prevent short-circuits that could cause similar sharp drops in aircraft pitch, the newspaper said Sunday.

The order to modify the wiring would apply to the nearly 800 MAX planes already produced, including those already in the hands of airlines, according to the report.

The Federal Aviation Authority said in a statement that it was working with the company to "address a recently discovered wiring issue" on the aircraft but did not confirm the Journal's report.

"The aircraft will be cleared for return to passenger service only after the FAA is satisfied that all safety-related issues are addressed," it added.

Boeing told AFP it was discussing the wiring issue with regulators but still expected the planes to return to service mid-year.

All 157 people aboard the Ethiopian Airlines jet were killed when it crashed shortly after take-off from Addis Ababa last March.

It followed the October 2018 crash of a 737 MAX operated by Lion Air in Indonesia, which killed 189 people when it crashed moments after

leaving Jakarta airport.

Boeing was accused of brushing off the concerns of engineers to release a "fundamentally flawed" aircraft by a damning US congressional report earlier this month.

The investigation also said the FAA had failed to exercise its oversight of the company and ignored warnings about the aircraft's safety flaws from its own experts.

© 2020 AFP

Citation: US regulators will force Boeing to rewire 737 MAX jets: report (2020, March 9) retrieved 25 April 2024 from <https://techxplore.com/news/2020-03-boeing-rewire-max-jets.html>

This document is subject to copyright. Apart from any fair dealing for the purpose of private study or research, no part may be reproduced without the written permission. The content is provided for information purposes only.