

NTSB says vehicle battery fires pose risks to 1st responders

January 13 2021, by Tom Krisher



This undated photo provided by National Transportation Safety Board, The Orange County Fire Authority battles a fire on a burning vehicle inside a garage in Orange County, Calif. When firefighters removed the SUV from the garage to assess the fire , they identified the fuel source as the SUV's high-voltage battery pack. U.S. safety investigators say electric vehicle fires pose risks to first responders, and manufacturers have inadequate guidelines to keep them safe. (Orange County Sheriff's Department/National Transportation Safety Board via AP)

Electric vehicle fires pose safety risks to first responders and guidelines from manufacturers about how to deal with them have been inadequate, according to U.S. investigators.

There are also gaps in industry safety standards and research on high-voltage lithium-ion battery fires, especially in high-speed, severe crashes, the National Transportation Safety Board said Wednesday.

The agency, which has no enforcement powers and can only make recommendations, called for manufacturers to write vehicle-specific response guides for fighting battery fires and limiting chemical thermal runaway and reignition. The guidelines also should include information on how to safely store vehicles with damaged lithium-ion batteries.

The recommendations come at a time when automakers are rolling out multiple new electric vehicle models, with many in the industry perceiving an inflection point in switching from gasoline power to cleaner electricity.

The agency in its Wednesday report also asked firefighter and auto towing associations to inform members about fire risks and how to deal with energy remaining in the battery after a crash, and on how to safely store a vehicle with a damaged battery.

And it's asking the National Highway Traffic Safety Administration to include the availability of an emergency response guide when it calculates five-star vehicle safety scores.

NHTSA also should build a coalition to research ways to de-energize batteries and reduce hazards from thermal runaway, a chemical reaction that causes uncontrolled battery temperature and pressure increases.

The NTSB started investigating battery fires after crashes and fires in Lake Forest and Mountain View, California, and in Ft. Lauderdale, Florida, in 2017 and 2018. It also probed a non-crash fire in West Hollywood, California. Three of the batteries reignited after fires were extinguished.

All four vehicles were made by Tesla, which is the top-selling electric vehicle maker in the U.S.

"The risks of electric shock and battery reignition/fire arise from the 'stranded' energy that remains in a damaged battery," the agency said.

In the August, 2017 fire in Lake Forest, a Tesla Model X battery caught fire after the vehicle left a road and crashed into a residential garage at a high speed. Thomas Barth, an NTSB engineer and highway investigator, said in an [agency video](#) that firefighters poured thousands of gallons of water onto the roof of the vehicle. "They didn't realize that they had to direct water onto the battery compartment under the car to cool the battery and stop the reaction causing the fire," he said.

In an 80-page report the NTSB wrote that a review of emergency response guidelines from 36 manufacturers found that all had ways to mitigate the risk of high-voltage shocks including methods for disconnecting the battery. But none of the guides spoke to limiting the risk of energy stored in the batteries, such as procedures for minimizing reignition or instructions on where and how to spray water to cool the batteries, the agency said.

One way to deal with damaged batteries is to pull them from the vehicle and soak them in a saltwater bath to discharge the energy, the NTSB wrote.

The National Fire Protection Association, which provides training to

first responders and tow companies, said it already has addressed most of the NTSB recommendations. Andrew Klock, emerging issues lead manager, says the group has put out training on how to extinguish battery fires, then jack up vehicles and douse the batteries with water to limit reignition.

The NFPA has trained about 250,000 first responders, but there are 1.2 million firefighters nationwide, Klock said.

In a statement, NHTSA said that last week it started a battery safety initiative to address growing concerns about electric vehicle and structure fires ignited by batteries. Under the initiative, the agency will analyze data, investigate fires and oversee investigations of electric vehicle crashes, the agency said.

The Alliance for Automotive Innovation, a large automaker trade group, said it will review the recommendations and is working with fire associations, NHTSA, the Society of Automotive Engineers and others to improve safety.

Messages were left Wednesday seeking comment from Tesla and the National Fire Protection Association.

© 2021 The Associated Press. All rights reserved. This material may not be published, broadcast, rewritten or redistributed without permission.

Citation: NTSB says vehicle battery fires pose risks to 1st responders (2021, January 13) retrieved 26 April 2024 from

<https://techxplore.com/news/2021-01-ntsb-vehicle-battery-pose-1st.html>

This document is subject to copyright. Apart from any fair dealing for the purpose of private study or research, no part may be reproduced without the written permission. The content is provided for information purposes only.