

Hyundai-Kia recall: turn signal can flash in wrong direction

September 30 2021



This combination of file photos shows the logo of Kia Motors, top and Hyundai logo, bottom. Hyundai and Kia are recalling more than 550,000 cars and

minivans in the U.S., Thursday, Sept. 30, 2021, because the turn signals can flash in the opposite direction of what the driver intended. The recall covers Hyundai's Sonata midsize car from the 2015 through 2015 model years, and Sonata gas-electric hybrids from 2016 and 2017. Kia's Sedona minivan from 2015 through 2017 also is affected. Credit: AP Photo, File

Hyundai and Kia are recalling more than 550,000 cars and minivans in the U.S. because the turn signals can flash in the opposite direction of what the driver intended.

The [recall](#) covers Hyundai's Sonata midsize car from the 2015 through 2017 model years, and Sonata gas-electric hybrids from 2016 and 2017. Kia's Sedona minivan from 2015 through 2017 also is affected.

Hyundai says software in a junction box may not properly interpreting signals. The Korean automaker says it doesn't know of any crashes or injuries from the problem.

Dealers will update the software at no cost to owners. Hyundai will begin mailing notification letters to customers on Nov. 19, while letters will go to Kia owners starting Nov. 12.

© 2021 The Associated Press. All rights reserved. This material may not be published, broadcast, rewritten or redistributed without permission.

Citation: Hyundai-Kia recall: turn signal can flash in wrong direction (2021, September 30) retrieved 9 April 2024 from <https://techxplore.com/news/2021-09-hyundai-kia-recall-wrong.html>

This document is subject to copyright. Apart from any fair dealing for the purpose of private study or research, no part may be reproduced without the written permission. The content is provided for information purposes only.
