

Tesla issues 2nd recall for obstructing pedestrian warning

April 14 2022



A sign bearing the company logo outside a Tesla store in Cherry Creek Mall in Denver, Feb. 9, 2019. Tesla is recalling nearly 595,000 vehicles in the U.S., Thursday, April 14, 2022, most for a second time, because a “Boombbox” function can play sounds over an external speaker and obscure audible warnings for pedestrians. Credit: AP Photo/David Zalubowski, File

Tesla is recalling nearly 595,000 vehicles in the U.S., most for a second time, because a "Boombox" function can play sounds over an external speaker and obscure audible warnings for pedestrians.

The electric car company says in government documents that the new recall will disable "Boombox" if owners are using a feature that lets them "summon" the vehicles at low speeds. The first recall in February disabled "Boombox" if the Teslas are in drive, neutral or reverse.

Both recalls will be done with online software updates.

The new recall covers certain 2020 through 2022 Model Y, X, and S vehicles, as well as the 2017 through 2022 Model 3. It was disclosed Thursday in documents posted by the National Highway Traffic Safety Administration.

"Boombox" allowed drivers to play preset or custom sounds while the vehicles are moving. This violated federal safety standards that require pedestrian warning noises for [electric cars](#), which make little noise when in motion.

The February recall came after the safety agency opened an investigation into the issue.

NHTSA said that in 2010, Congress required electric and [hybrid vehicles](#) to make pedestrian warning noises. The law required agency rules to stop manufacturers from allowing anyone other than an automaker or dealer to modify the pedestrian alert sounds,

Also Thursday, NHTSA posted [documents](#) showing that Tesla is recalling more than 7,000 Model X SUVs from the 2021 and 2022 because the side curtain air bags may not inflate as intended in a crash when the windows are lowered.

Owners will be notified in early June, and service centers will replace the left and right front-row side air bags. The problem was discovered in tests done by Tesla.

© 2022 The Associated Press. All rights reserved. This material may not be published, broadcast, rewritten or redistributed without permission.

Citation: Tesla issues 2nd recall for obstructing pedestrian warning (2022, April 14) retrieved 6 May 2024 from <https://techxplore.com/news/2022-04-tesla-issues-2nd-recall-obstructing.html>

This document is subject to copyright. Apart from any fair dealing for the purpose of private study or research, no part may be reproduced without the written permission. The content is provided for information purposes only.