

GM recall: Side air bags can explode in Chevy, GMC pickups

9 July 2021



This Feb. 11, 2016 file photo shows the GMC logo on display at the Pittsburgh International Auto Show in Pittsburgh. General Motors is recalling more than 400,000 pickup trucks in the U.S. because the side air bags can explode without warning and spew parts into the cabin, Friday, July 9, 2021. The recall covers certain 2015 and 2016 Chevrolet and GMC Sierra 1500, 2500, and 3500 trucks. Credit: AP Photo/Gene J. Puskar

General Motors is recalling more than 400,000 pickup trucks in the U.S. because the side air bags can explode without warning and spew parts into the cabin.

The recall covers certain 2015 and 2016 Chevrolet and GMC Sierra 1500, 2500, and 3500 trucks.

Documents posted Friday by U.S. safety regulators say the air bag inflator can rupture or the end cap can fly off on both sides of the trucks. Documents say three inflators ruptured in 2015 Silverados last month, one in Florida and two in Texas. All three trucks were unoccupied at the time, and GM says it has no reports of injuries..

The company says a manufacturing defect allowed moisture into the inflator while it was being

manufactured, causing corrosion. The inflators were made in Mexico by Joyson Safety Systems.

Dealers will replace both side air bag modules. The company says it has a limited number of replacement parts available. Owners will be notified starting Aug. 16 and they'll get a second letter when parts are widely available.

About 9,000 of the [trucks](#) were recalled last year for the same problem.

© 2021 The Associated Press. All rights reserved. This material may not be published, broadcast, rewritten or redistributed without permission.

APA citation: GM recall: Side air bags can explode in Chevy, GMC pickups (2021, July 9) retrieved 23 October 2021 from <https://techxplore.com/news/2021-07-gm-recall-side-air-bags.html>

This document is subject to copyright. Apart from any fair dealing for the purpose of private study or research, no part may be reproduced without the written permission. The content is provided for information purposes only.